HISTORIC PROPERTY INVEN	ITORY FORM	Ot	ate of Washington, Department of Community Development Ifice of Archaeology and Historic Preservation I 1 West 21st Avenue, KL-11
IDENTIFICATION SECTION	7 10 06	OI	ympia, WA 98504 (206) 753-4011
Field Site No. 70 OAHP No. Date Rec		LOCATION SECTION	-1207 14th Avenue
Site Name Historic Lovell Groves Bu	ilding	Address1203-1203	-1207 14th Avenue
Common		City/Town/County/Zip Code	ongview, Cowlitz 98632
Field Recorder Historic Preserva	ation Commission		33 % Section NE  % % Section SW
Owner's Name Gary and Jean Por	oe	Tax No. / Parcel No. 0162	
Address 2240 Washington W		Quadrangle or map name Kels	so, Wash
City/State/Zip Code Longview, WA 986		UTM References, Zone, 10 E.	asting 504100 Northing 5108950
City/State/Zip Code Lottg / 12.11 11 201	<u> </u>	Plet/Block/Lot Longvie	ew #11 Blk 96 Lot 11
Status		Supplemental Map(s)	
X Survey/Inventory	PHOTOGRAPHY	Oupplemental Map(a)	
National Register	Photography Neg. No		and a brief distriction with the
State Register	(Roll No. & Frame No.)	20	
Determined Eligible	View of	The second secon	
Determined Not Eligible	Date	The second secon	
Other (HABS, HAER, NHL)	Date		
Local Designation			
Classification District Site Building	Structure Dbject		
District Status NR SR LR INV			
Contributing Non-Contributing			
District/Thematic Nomination Name		Tomas de la company	
DESCRIPTION OF STOLEN	Deef Tunn	Danielle's 4th	ZOOME CALL
DESCRIPTION SECTION	Roof Type  ☐ Gable ☐ Hip	Marilos	
Materials & Features/Structural Types	☐ Gable ☐ Hip ☐ Flat ☐ Pyramidal		
Building Type Commercial			
Plan Rectangular	☐ Monitor ☑ Other (specify) ☐ Gambrel   BOW String Tru	I STATE OF THE PARTY OF THE PAR	
Structural System Poured Concrete	- Chad		
No. of Stories One with storage a	DOVE Roof Material	THE STORES	TO THE STATE OF TH
Cladding (Exterior Wall Surfaces)			
Log	Composition		The same of the sa
☐ Horizontal Wood Siding ☐ Rustic / Drop	☐ Slate		
☐ Clapboard	∑ Tar/Built-Up	No. of the second secon	11 13 '9 7
☐ Wood Shingle	Tile		
Board and Batten	Metal (specify)	High Styles / Forms (check one or	more of the following)
☐ Vertical Board	Other (specify)	Greek Revival	Spanish Colonial Revival / Mediterranean
☐ Asbestos / Asphalt ☐ Brick	Not visible	Gothic Revival	☐ Tudor Revival
Stone	Foundation	☐ Italianate	Craftsman / Arts & Crafts
⊠ Stucco		Second Empire	Bungalow
Terra Cotta	Log Concrete Post & Pier Block	Romanesque Revival	Prairie Style
☐ Concrete / Concrete Block	Stone Spoured	Stick Style	Art Deco/Art Moderne
☐ Vinyl/Aluminum Siding ☐ Metal (specify) — 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	☐ Brick ☐ Other (specify)	Queen Anne	Rustic Style
Other (specify) Original 4x4 Til		Shingle Style	☐ International Style ☐ Northwest Style
		Colonial Revival	☐ Northwest Style  ☑ Commercial Vernacular
(Include detailed description in		☐ Beaux Arts / Neoclassical ☐ Chicago / Commercial Style	Residential Vernacular (see below)
Integrity Description of Physical Appearance) Intact	Slight Moderate Extensive	American Foursquare	Other (specify)
		☐ Mission Revival	_ Carter (opcour)
Changes to plan		- Imagion (terira)	
Changes to windows		Vernacular House Types	
Changes to interior		Gable front	Cross gable
Other (specify)		☐ Gable front and wing	Pyramidal/Hipped
DCD 10/86 -1209- 3		Side gable	Other (specify)

## NARRATIVE SECTION

Study Unit Themes (check one or more of the following)			
☐ Agriculture	Conservation	☐ Politics/Government/Law	
Architecture / Landscape Architecture	☐ Education	Religion	
☐ Arts	☐ Entertainment / Recreation	Science & Engineering	
Commerce	Ethnic Heritage (specify)	Social Movements / Organizations	
Communications	☐ Health / Medicine	Transportation	
☐ Community Planning / Development	☐ Manufacturing / Industry	Other (specify)	
	☐ Military	Study Unit Sub-Theme(s) (specify)	
Statement of Significance			
Date of Construction 1946	Architect/Engineer/Builder Wick, Ghilgers & S	Scott Portland	
In the opinion of the surveyor, this property appears	to meet the criteria of the National Register of Historic Places		
In the opinion of the surveyor, this property is locate	d in a potential historic district (National and / or local).		

This building is typical of commercial vernacular constructed in downtown Longview. Its three retail bays have had at least twenty tenants over the years as listed on the attached sheet. L.M. Groves had the building constructed to house his Groves Quality Bakery from 1946-52.

Description of Physical Appearance The 50' x 120' building sits at the northwest corner of the Hemlock Street and 14th Avenue intersection. The building primarily fronts on 14th Avenue with three storefronts each with their own separate entrance and large display window. Each entrance door has a wide wood surround, punctuated with a flip open mail box slot centered beneath the door's plate glass panel inset. A transom window is above each door. The kick plates below the display windows are red tile in 1203 and 1205; and glass block in 1207. The change to glass block and its wider placement and shorter display window do not appear original to the building. The upper facade is stucco in 1203 and 1205; and corrugated metal with matching awning above 1207. A flat angled awning which appears original is above 1203 14th. The 1203 14th storefront display window wraps around to the Hemlock Street facade. Also on the Hemlock side, two additional entrance doors are separated by a series of large display windows, one of which has been blocked, with triple divided transom windows above. An original 6' x 6' double sided freight elevator transported flour and baking supplies within the building. It is currently non-functioning and one door is blocked over. A roll up rear delivery door off the alley leads immediately to an interior ramp which descends into the basement where bakery items were stored. A series of bow string trusses support the roof.

The building was remodeled in 1997.